

## Indicator bracket panel contacted mounting

### A. Indicator and Bracket



### B. Mounting bracket establishment

( Indicator in panel cutting hole after insertion.... )

#### 1. Bracket horizontally put in case first time grooves.



2. Bracket of picture-1 condition makes be perpendicular and makes return.



3. When the picture-2 comes like becomes the upright, bolting bracket.



#### 4. Indicator bracket establishment completion.



Uses establishment method as bracket and fixes in panel.